

| | | | |
|---|----------|------------------|--|
| State of California — The Resources Agency DEPARTMENT OF PARKS AND RECREATION PRIMARY RECORD | | Primary | |
| | | HRI # | |
| | | Trinomial | |
| | | NRHP Status Code | |
| Other | | | |
| Review Code | Reviewer | Date | |

Page 1 of 4

*Resource Name or #: (Assigned by Recorder) 2923 Fruitland Ave.

P1. Other Identifier: _____

*P2. Location: **Not for Publication** ☒ **Unrestricted** *a. County Los Angeles

and (P2b and P2c or P2d. Attach a Location Map as necessary.)

*b. USGS 7.5' Quad South Gate Date 1978 T 2S ; R 13W ; 1/4 of 1/4 of Sec 1 ; S.B. B.M

c. Address 2923 Fruitland Ave. City Vernon Zip 90058

d. UTM: (Give more than one for large and/or linear resources) Zone: 11 ; 1 mE/ 1 mN

e. Other Locational Data: (e.g. parcel #, directions to resource, elevation, etc., as appropriate)

APN # 6303-029-001

*P3a. Description (Describe resource and its major elements. Include design, materials, condition, alterations, size, setting, and boundaries)

The Owens-Illinois GLass Co. structure is a multi-story industrial complex. The façade is curved in design and constructed of masonry block. Two banks of stationary glass windows (glass block) run the length of the façade, on the upper level of the structure, broken up by block coursework. Two lower window segments are at each end of the façade. Louvered windows are spaced equally within the glass block segments. The entry is oversized and can facilitate tractor trailers. Two round, non-descript columns are spaced equally apart within the entryway. The structure is in fair to good condition

The setting is a mix of industrial and commercial. The building, located along S. Soto Street between Fruitland Ave. and E 50th Street, Fronts on Fruitland Ave. The structure is surrounded by other light industrial buildings and railroad spurs.

*P3b. Resource Attributes: (List attributes and codes) HP8 (industrial)

*P4. Resources present: ☒ Building ☐ Structure ☐ Object ☐ Site ☐ District ☐ Element of District ☐ Other (isolates, etc.)

P5a. Photograph or Drawing (Photograph required for buildings, structures, and objects)

See Continuation sheet for photos.

P5b. Description of Photo: (View, date, accession #)

See Continuation sheet for photos.

*P6. Date Constructed/Age and

Sources: ☒ Historic

☐ Prehistoric ☐ Both

calculate

*P7. Owner and Address:

Owens Illinois Glass Container Inc.
2923 Fruitland Ave.
Vernon, Ca 90058

*P8. Recorded by: (Name, affiliation, and address)

Kelly Heidecker and Jeff Creighton
Parsons
2233 Watt Ave, Suite #330
Sacramento, CA 95825

*P9. Date Recorded:

June 30, 2002

*P10. Survey Type: (Describe)

Intensive

*P11. Report Citation: (Cite survey report and other sources, or enter "none.") Malburg Generating Station Project Cultural Resources Inventory Report

*Attachments: NONE ☒ Location Map ☐ Sketch Map ☐ Continuation Sheet ☒ Building, Structure, and Object Record

☐ Archaeological Record ☐ District Record ☐ Linear Feature Record ☐ Milling Station Record ☐ Rock Art Record

☐ Artifact Record ☐ Photograph Record ☐ Other (List): _____